


Použití - Usage - Applikation - Употребление



HSS  
Co8

ρ	D js 14	D <sub>1</sub> ~	l	L	d h 6	CODE 580718	IDENT.
1°	5	5,7	20	73	10	•	.0105
1°	8	9,1	32	95	12	•	.0108
1°	12	13,7	50	118	16	•	.0112
1°	20	22,8	80	155	20	•	.0120
2°	5	6,4	20	74	10	•	.0205
2°	8	10,2	32	95	12	•	.0208
2°	12	15,5	50	118	16	•	.0212
2°	20	25,6	80	160	25	•	.0220
3°	5	7,1	20	74	10	•	.0305
3°	8	11,4	32	95	12	•	.0308
3°	12	17,2	50	120	20	•	.0312
3°	20	28,4	80	160	25	•	.0320
5°	5	8,5	20	74	10	•	.0505
5°	8	13,6	32	98	16	•	.0508
5°	12	20,7	50	120	20	•	.0512
5°	20	34	80	165	32	•	.0520
7°	5	9,9	20	80	12	•	.0705
7°	8	15,9	32	98	16	•	.0708
7°	12	24,3	50	130	25	•	.0712
7°	20	39,6	80	165	32	•	.0720
10°	5	12,1	20	80	12	•	.1005
10°	8	19,3	32	100	20	•	.1008
10°	12	29,6	50	130	25	•	.1012
10°	20	48,2	80	165	32	•	.1020

